

CT-64 POWER SUPPLY WIRING DIAGRAM